MERCEDES-BENZ SPRINTER 314 L2H1 Airco!



Itemno Kind Specification Matriculation year Mileage Chassisnumber WDB9106331P033505

305589 Van Closed Van 2019/06 250,230 km



4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Wheelbase Suspension type

Cabin

Cabin type Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Color Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Back doors

105 Kw (143 Hp) diesel 6 Timing chain Manual 6

2

4x2

1,487 kg

2,013 kg

3,500 kg

392 cm

single cabin

1

None

white

spring suspension

333 cm 177 cm 173 cm 60 cm 160 cm None Double door

Contact information



info@kleyn.com Tel: +31 183 668 444

Chairs Number of seats

Seat cover

Remarks Remarks

Tyres/Wheels

Sparewheel Spare tire profile 2 cloth

L2H1 Airco!


5 mm

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

0000


VANS KLEYN KLEYN KLEYN GROUP KLEYN KLEYN TRUGKS KLEYN SERVIC

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state

Does not meet requirements