OPEL COMBO 1.3 L2H1 Airco Maxi!



Itemno Kind Specification Matriculation year Mileage Chassisnumber W0L6WYC1AF9556517

305590 Van Compact panel van 2014 / 11 165,174 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Wheelbase Suspension type

Cabin

Cabin type Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Color Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

2 4x2 1,025 kg 1,360 kg 2,385 kg 500 kg 1,000 kg

311 cm coil spring suspension

single cabin

1 None

white

66 Kw (90 Hp) diesel 5 Timing chain Manual 5

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Roof-rack Back doors

Chairs Number of seats Seat cover

Remarks Remarks

Tyres/Wheels Sparewheel

193 cm 147 cm 120 cm 56 cm standard Double door

2 cloth

1 2H1 Airco Maxi!

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Liectrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

VANS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state

Does not meet requirements