# **CITROEN JUMPER 2.2 L2H2 Airco Nieuw!**



305623 Itemno Kind Van Specification Frigo Matriculation year 2023 / 11 Mileage 368 km

Chassisnumber VF7YCBPFBPG040810

Technical condition

L2H2 Airco Nieuw Versterkte-Bladveer







**Price €45999** 



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# **Equipment**

### Chassis

Number of axles 2 Configuration 4x2

### Cabin

Cabin type single cabin

Airconditioning

Parking assistance Front and back

Electric windows Electric mirrors

Partition

white Color

Reversing camera

#### **Drivetrain**

Engine capacity 103 Kw (140 Hp)

Euro Gearbox kind Manual Number of Gears

Power steering

**ABS ASR** 

### Superstructure

Roof-rack None Sidedoors

Back doors Double door

# **Chairs**

Number of seats 3 Seat cover cloth

# Remarks

Remarks L2H2 Airco Nieuw

> Versterkte-Bladveer 140Pk Navi + CarPlay Direct

Leverbaar!

### **Contact information**



info@kleyn.com Tel: +31 183 668 444

### Certified and professional













Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

# **Dimensions**







Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# **Inspection report**

### Chassis

Dashboard display codes

Electrical

# 00000

### Cabin

Internal 00000 00000 External

Steering column 00000

Suspension 00000

00000 Chassis Wheelsuspension 00000

Brakes 00000

### **Drivetrain**

Engine, general 99999

00000 Cooling system

33333 Fuel system 00000 Exhaust system

Greasing system 00000

Gearbox 00000

Clutch 00000 Drivetrain 00000

Superstructure

Superstructure 00000 00000 Internal condition 00000 External condition

### Refrigiration unit

Systems 00000

# **Contact information**



info@kleyn.com Tel: +31 183 668 444

# Tyres/Wheels

Tyres



# Tires and axles



Tire size: 0/0R0,0



Tire size: 0/0R0,0

### Legenda for inspection report

Very good state Good state

Reasonable state Moderate state

Does not meet requirements