MERCEDES-BENZ VITO 114 CDI



Itemno Kind Specification Matriculation year Mileage Chassisnumber WDF44760313273362

306974 Van Closed Van 2017/04 162,963 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Parking heater Number of airbags Parking assistance Coloured windows Electric windows Electric mirrors Partition Color

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Power steering ABS ASR

2 4x2 913 kg 2,137 kg 3,050 kg 750 kg 2,000 kg

320 cm coil spring suspension

single cabin

4 Front and back

Brown

100 Kw (136 Hp) diesel 6 Timing chain Automatic

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Roof-rack Back doors

Chairs

Number of seats Seat cover

Tyres/Wheels

Sparewheel

249 cm 165 cm 130 cm 58 cm None Double door

2 cloth

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

VANS KLEYN KLEYN GROUP KLEYN KLEYN TRAILERS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



coil spring suspension Disc brakes

Legenda for inspection report	
	Very good state
	Good state
00000	Reasonable state
00000	Moderate state
00000	Does not meet requirements