VOLKSWAGEN CRAFTER 2.0 TDI 140 L2H1



Itemno Kind Specification Matriculation year Mileage Chassisnumber WV1ZZZ2EZG6019449

307511 Van Closed Van 2015 / 11 226,860 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Own weight Gross vehicle weight Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Color Reversing camera

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

2 4x2 2,206 kg 3,200 kg

367 cm spring suspension

single cabin

2 Front and back

Yellow

100 Kw (136 Hp) diesel 5 Timing belt Manual 6

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Rear step Roof-rack Sidedoors Back doors

Chairs

Number of seats Seat cover

Remarks Remarks

Tyres/Wheels

Sparewheel Spare tire profile 325 cm 178 cm 162 cm 68 cm 152 cm

None 1 Double door

3 cloth

L2H1, airco, navi, pdc, trekhaak

8 mm

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

VANS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



 Legenda for inspection report

 Very good state

 Good state

 Reasonable state

 Noderate state

 Does not meet requirements