MERCEDES-BENZ SPRINTER 519 CDI



Itemno308085KindVanSpecificationChassis Cabin

Specification Chassis Cabin
Matriculation year 2024 / 02
Mileage 13 km

Chassisnumber W1V9071551N210865

W1V9071551N210865

Technical condition

Remarks NIEUW 10 KMS AIRCO 190 PK!

Sparewheel

(A15)





Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis Tyres/Wheels

Number of axles 2
Configuration 4x2

Twin tires

Chassis-height 85 cm Wheelbase 433 cm

Suspension type spring suspension

Cabin

Cabin type single cabin

Cruise control

Airconditioning

Number of airbags 1
Parking assistance None

Electric windows

Electric mirrors

Color white

Drivetrain

Engine capacity 140 Kw (190 Hp)

Fuel type diesel
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6

Power steering

ABS ASR

Superstructure

Build kind Extra long - Standard roof

Roof-rack None

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks NIEUW 10 KMS AIRCO 190

PK!

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional











Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis

Dashboard display codes 00000 Electrical 00000

Cabin Internal 00000 00000 External Steering column 00000 Suspension 00000 00000 Chassis Wheelsuspension 00000 Brakes 00000

Drivetrain

Engine, general 99999 00000 Cooling system 33333 Fuel system 00000 Exhaust system Greasing system 99999 Gearbox 00000 Clutch 00000 Drivetrain 00000

Tyres/Wheels

00000 Tyres



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Tire size: 205/75R16,0 spring suspension Disc brakes



Tire size: 205/75R16,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state Good state Reasonable state Moderate state

Does not meet requirements