VOLKSWAGEN CRAFTER



Itemno Kind Specification Matriculation year Mileage Chassisnumber 308278 Van Closed Van 2017 / 10 283,871 km

Chassisnumber WV1ZZZSYZJ9003582

Technical condition **Remarks**

(A15)

Price €12750



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Color Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR 2 4x2 500 kg 1,989 kg 2,489 kg 750 kg 3,000 kg

364 cm spring suspension

single cabin

1 None

white

103 Kw (140 Hp) diesel 6 Timing belt Manual 6

Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Sidedoors Back doors

Chairs

Number of seats Seat cover

Tyres/Wheels

Sparewheel

178 cm 191 cm 58 cm 181 cm None 1 Double door

320 cm

3 cloth

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	000
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	000
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements