MERCEDES-BENZ SPRINTER 316



Itemno Kind Specification Matriculation year Mileage Chassisnumber WDB9061351N712676

308543 Van Closed box 2017/06 221,102 km



4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Parking Airco Parking heater Number of airbags Parking assistance Electric windows Electric mirrors **GPS** navigation Color Reversing camera

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 750 kg 2,750 kg 3,500 kg 433 cm spring suspension

single cabin

1 None

2

white

120 Kw (163 Hp) diesel 6 Timing chain Manual 6

Superstructure

NAP

Build kind Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Back doors

Chairs

Number of seats Seat cover Comfort seat

Remarks

Remarks

Tyres/Wheels Sparewheel

Extra long - Standard roof 439 cm 212 cm 219 cm 92 cm 212 cm None Single door

2 cloth left

AIRCO NAV CRUISE EURO6!

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	

Tyres/Wheels

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren

Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state

Moderate state Does not meet requirements