

FIAT E-DUCATO ELECTRIC L3H2 47kWh NIEUW



Itemno 295951
Kind Van
Specification Closed Van
Matriculation year 2022 / 07
Mileage 694 km

Chassisnumber
ZFA25000002T56893

Technical condition

Remarks
NIEUW, direct leverbaar, L3H2, 47kWh,
(A15)

Price € 37450

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 1,085 kg
Own weight 2,415 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Wheelbase 404 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 1
Parking assistance Front and back
Coloured windows ✓
Electric windows ✓
Electric mirrors ✓
Partition ✓
GPS navigation ✓
Color white
Reversing camera ✓

Drivetrain

Engine capacity (0 Hp)
Fuel type electrical
Gearbox kind Automatic
Power steering ✓
ABS ✓

Superstructure

Inner box length 360 cm
Inner box width 186 cm
Inner box height 190 cm
Load bed height 56 cm
Netto height 176 cm
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks NIEUW, direct leverbaar, L3H2,
47kWh, VOL ELEKTRISCH

Tyres/Wheels

Sparewheel ✓
Spare tire profile 8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Wheelsuspension

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Gearbox

Clutch

Drivetrain

Superstructure

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 0/0R0,0
coil spring suspension
Disc brakes



Tire size: 0/0R0,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements