

CITROEN JUMPER 2.0 HDI FRIGO L3H2



Itemno 296981
Kind Van
Specification Frigo
Matriculation year 2022 / 07
Mileage 942 km

Chassisnumber
VF7YCAPFC12U72426

Technical condition 

Remarks
L3H2, koelwagen, D/N, airco, navi, 700
(A15)

Price €38900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,188 kg
Own weight	2,312 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Wheelbase	404 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	Back
Electric windows	
Electric mirrors	
Partition	
Color	white
Heated mirrors	

Drivetrain

Engine capacity	88 Kw (120 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Inner box length	338 cm
Inner box width	165 cm
Inner box height	179 cm
Load bed height	60 cm
Netto height	165 cm
Rear step	
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Refrigeration unit

Enginemaker frigo-unit	Thermoking
Enginetype frigo-unit	ce series
Enginetype frigo-unit	Compressor / electrical
Type of cooling	Cooling
Day/night cooling	day and night cooling

Remarks

Remarks	L3H2, koelwagen, D/N, airco, navi, 700 km.!!
---------	--

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**


Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 

Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 


Wheelsuspension 

Brakes 

Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

Superstructure

Internal condition 

External condition 

Refrigeration unit

Systems 

Tyres/Wheels

Tyres 

Tires and axles



Tire size: 215/70R15,0
coil spring suspension
Disc brakes



Tire size: 215/70R15,0
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

 Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements