

## M.A.N. TGE 3.180



Itemno 298318  
Kind Van  
Specification Closed Van  
Matriculation year 2020 / 06  
Mileage 159,464 km

**Chassisnumber**  
WMA03VUY2L9008334

Technical condition

### Remarks

( A15 )

**Price €20950**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,365 kg
Own weight	2,135 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,000 kg
Towing bracket	
Wheelbase	449 cm
Suspension type	spring suspension

### Cabin

Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	None
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
Heated mirrors	
Reversing camera	

### Drivetrain

Engine capacity	130 Kw (177 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Number of Gears	8
Power steering	
ABS	
ASR	

### Superstructure

Build kind	Extra Long - High roof
Inner box length	405 cm
Inner box width	177 cm
Inner box height	193 cm
Load bed height	60 cm
Netto height	182 cm
Rear step	
Roof-rack	None
Sidedoors	1
Back doors	Double door

### Chairs

Number of seats	3
Seat cover	cloth
Comfort seat	left

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 205/75R16,0  
coil spring suspension  
Disc brakes



Tire size: 205/75R16,0  
spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements