

## MERCEDES-BENZ SPRINTER 314 L2H2 Airco LED!



Itemno 298916  
Kind Van  
Specification Closed Van  
Matriculation year 2020 / 07  
Mileage 159,785 km

**Chassisnumber**  
W1V9106331P259624

Technical condition

**Remarks**  
L2H2 Airco LED 143PK Euro6 1e Eigenaar!  
( A15 )



**Price €21900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 1,334 kg  
Own weight 2,166 kg  
Gross vehicle weight 3,500 kg  
Wheelbase 392 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Airconditioning  
Number of airbags 1  
Parking assistance None  
Electric windows  
Electric mirrors  
Partition  
Color white  
Heated mirrors

### Drivetrain

Engine capacity 105 Kw (143 Hp)  
Fuel type diesel  
Euro 6  
Distribution type Timing chain  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Inner box length 327 cm  
Inner box width 178 cm  
Inner box height 200 cm  
Load bed height 60 cm  
Netto height 190 cm  
Rear step  
Roof-rack None  
Back doors Double door

### Chairs

Number of seats 3  
Seat cover cloth

### Remarks

Remarks L2H2 Airco LED 143PK Euro6  
1e Eigenaar!

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430


SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes 

Electrical 

### Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Wheelsuspension 

Brakes 

### Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

### Superstructure

Internal condition 

External condition 

### Tyres/Wheels

Tyres 

## Tires and axles



1  
Tire size: 225/65R16,0  
coil spring suspension  
Disc brakes



2  
Tire size: 65/0R16,0  
spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

 Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements