

MERCEDES-BENZ SPRINTER 314 L2H2 Laadklep Air



Itemno 302523
Kind Van
Specification Closed Van
Matriculation year 2018 / 02
Mileage 162,791 km

Chassisnumber
WDB9066331P582216

Technical condition

Remarks
L2H2 Airco Laadklep 143Pk Mf-Stuurwiel
(A15)

Price € 20900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,475 kg
Gross vehicle weight 3,500 kg
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Parking heater ✓
Number of airbags 1
Parking assistance None
Coloured windows ✓
Electric windows ✓
Electric mirrors ✓
Partition ✓
Color white
Heated mirrors ✓
Reversing camera ✓

Drivetrain

Engine capacity 105 Kw (143 Hp)
Fuel type diesel
Euro 6
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 326 cm
Inner box width 178 cm
Inner box height 191 cm
Load bed height 68 cm
Netto height 181 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 2
Seat cover cloth

Taillift

Taillift ✓
Tail-lift kind normal
Tail-lift capacity 750 kg
Tail-lift make BAR Cargolift
Tail-lift size 176x132

Remarks

Remarks L2H2 Airco Laadklep 143Pk
Mf-Stuurwiel Euro6!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 235/65R16,0
spring suspension

2



Tire size: 235/65R16,0
spring suspension

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements