RENAULT MASTER 2.3 DCI



Itemno Kind Specification Matriculation year Mileage Chassisnumber VF1MAFCYN53261031

304184 Van Closed Van 2015 / 10 239,721 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Color Heated mirrors

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 1,440 kg 1,860 kg 3,300 kg 750 kg 2,500 kg

2

368 cm spring suspension

single cabin

2 Back

white

100 Kw (136 Hp) diesel 5 Timing chain Manual 6

Superstructure

Build kind Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Sidedoors Back doors

Chairs

Number of seats Seat cover

Remarks

Remarks

Medium length - High roof 300 cm 175 cm 187 cm 58 cm 180 cm standard 1 Double door

2 cloth

AC

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444

0000


VANS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements