

MERCEDES-BENZ VITO 110 CDI



Itemno 304360
Kind Van
Specification Closed Van
Matriculation year 2014 / 03
Mileage 142,111 km

Chassisnumber
WDF63960513865304

Technical condition
Remarks

(A15)



Price €8450

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 610 kg
Own weight 1,890 kg
Gross vehicle weight 2,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 2,000 kg
Wheelbase 343 cm
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Number of airbags 1
Parking assistance None
Electric windows
Electric mirrors
Partition
Color Silver
Metallic

Drivetrain

Engine capacity 70 Kw (95 Hp)
Fuel type diesel
Euro 5
Distribution type Timing chain
Gearbox kind Manual
Power steering
ABS
ASR

Superstructure

Build kind Extra long - Standard roof
Inner box length 268 cm
Inner box width 165 cm
Inner box height 135 cm
Load bed height 57 cm
Netto height 123 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Tyres/Wheels

Sparewheel
Spare tire profile 7 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 205/65R16,0
coil spring suspension
Disc brakes



Tire size: 205/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements