## **OPEL VIVARO 1.6**



Itemno 304434 Kind Van Specification Closed Van Matriculation year 2021 / 08 Mileage 83,187 km

Chassisnumber VXEVFAHKKM7839006

Technical condition

**Price €16950** 









Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

## **Equipment**

## **Chassis**

Number of axles Configuration 4x2 Loading Capacity 1,483 kg 1,617 kg Own weight 3,100 kg Gross vehicle weight Unbraked towing capacity 750 kg Braked towing capacity, center 2,500 kg

Wheelbase 328 cm

Suspension type coil spring suspension

### Cabin

Cabin type single cabin

Cruise control Airconditioning

Number of airbags

Front and back Parking assistance

Electric windows Electric mirrors Partition

**GPS** navigation

Color white

Reversing camera

### **Drivetrain**

Engine capacity 90 Kw (122 Hp)

Fuel type diesel Euro

Distribution type Timing belt Gearbox kind Manual Number of Gears 6

Power steering

ABS **ASR** 

## Superstructure

Build kind Standard length - Standard roof Inner box length 251 cm 163 cm Inner box width 140 cm Inner box heigth Load bed heigth 59 cm 122 cm Netto height Roof-rack None Sidedoors

Back doors Double door

#### Chairs

Number of seats 3 Seat cover skai

## Remarks

Remarks AC

## Tyres/Wheels

Sparewheel

### **Contact information**



info@kleyn.com Tel: +31 183 668 444

### Certified and professional














Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## **Dimensions**



# KLEYN VANS

EYN KLEYN KLEYN TRAILERS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

## **Inspection report**

## Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

## Drivetrain

Engine, general 0000 00000 Cooling system 00000 Fuel system Exhaust system 00000 Greasing system Gearbox 3330 Clutch 00000 Drivetrain 33330

### Superstructure

Internal condition

External condition

## Tyres/Wheels

Tyres

## **Tires and axles**



Tire size: 215/65R16,0 coil spring suspension Disc brakes



Tire size: 215/65R16,0 coil spring suspension Disc brakes

### **Contact information**



info@kleyn.com Tel: +31 183 668 444

### Legenda for inspection report

Very good state
Good state
Reasonable state
Moderate state
Does not meet requirements