

MERCEDES-BENZ SPRINTER 316 L3H2 Maxi Mbus A



Itemno 304495
Kind Van
Specification Closed Van
Matriculation year 2020 / 10
Mileage 96,831 km

Chassisnumber
W1V9076351P290604

Technical condition

Remarks
L3H2 Maxi Mbus Airco Camera
(A15)

Price €28900



Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,062 kg
Own weight	2,438 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Silver
Metallic	
Heated mirrors	
Reversing camera	

Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Inner box length	430 cm
Inner box width	178 cm
Inner box height	191 cm
Load bed height	72 cm
Netto height	181 cm
Rear step	
Roof-rack	None
Sidedoors	1
Back doors	Single door

Chairs

Number of seats	3
Seat cover	cloth
Comfort seat	left

Remarks

Remarks	L3H2 Maxi Mbus Airco Camera Parkeersensoren 163Pk Euro6!
---------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements