

VOLKSWAGEN CRAFTER 2.0 TDI L3H2 DC Airco!



Itemno 305113
Kind Van
Specification Closed Van
Matriculation year 2018 / 10
Mileage 171,797 km

Chassisnumber
WV1ZZSYZK9008433

Technical condition

Remarks
L3H2 (L2H1) DC Dubbele cabine Airco,
(A15)



Price € 19750

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	1,400 kg
Own weight	2,100 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Towing bracket	✓
Wheelbase	364 cm
Suspension type	spring suspension

Cabin

Cabin type	Double cabin
Cabin type	double cabin
Cabin type	Dubbele cabine
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
Radio/cassette	✓
Color	white
maintenance Guide	✓
Heated mirrors	✓

Drivetrain

Engine capacity	75 Kw (102 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	✓

Superstructure

Build kind	Medium length - Standard roof
Inner box length	235 cm
Inner box width	173 cm
Inner box height	169 cm
Load bed height	56 cm
Netto height	160 cm
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	6
Seat cover	skai

Remarks

Remarks	L3H2 (L2H1) DC Dubbele cabine Airco, Trekhaak, Leer, 6 persoons, 1e Eigenaar NAP!
---------	---

Tyres/Wheels

Sparewheel	✓
Spare tire profile	8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 205/75R16,0
coil spring suspension
Disc brakes



2
Tire size: 205/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements