

MERCEDES-BENZ SPRINTER 314 CDI



Itemno 305122
Kind Van
Specification Closed Van
Matriculation year 2015 / 12
Mileage 200,543 km

Chassisnumber
WDB9066311P199439

Technical condition 

Remarks
AC AUTOMAAT CRUISE 2X SCHUIFDEUR
(A15)



Price €11950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,454 kg
Own weight	2,046 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Wheelbase	325 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Electric windows	
Electric mirrors	
Partition	
Color	white
Heated mirrors	

Drivetrain

Engine capacity	95 Kw (129 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	
ABS	
ASR	

Superstructure

Build kind	Standard length - Standard roof
Inner box length	250 cm
Inner box width	177 cm
Inner box height	176 cm
Load bed height	68 cm
Rear step	
Roof-rack	standard
Back doors	Double door
Workshop equipment	

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	AC AUTOMAAT CRUISE 2X SCHUIFDEUR
---------	----------------------------------

Tyres/Wheels

Sparewheel	
Spare tire profile	8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Wheelsuspension

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements