

VOLKSWAGEN CRAFTER 35 2.0 TDI



Itemno 305181
Kind Van
Specification Closed Van
Matriculation year 2021 / 01
Mileage 124,861 km

Chassisnumber
WV1ZZSYZM9035832

Technical condition

Remarks
MAXI AC 140 PK
(A15)



Price €24950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 1,406 kg
Own weight 2,094 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 3,000 kg
Wheelbase 449 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Airconditioning
Number of airbags 1
Parking assistance None
Electric windows
Electric mirrors
Partition
Color white
Heated mirrors

Drivetrain

Engine capacity 103 Kw (140 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Build kind Extra Long - High roof
Inner box length 410 cm
Inner box width 177 cm
Inner box height 197 cm
Load bed height 56 cm
Netto height 183 cm
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks MAXI AC 140 PK

Tyres/Wheels

Sparewheel
Spare tire profile 8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 235/65R16,0
coil spring suspension
Disc brakes



2

Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements