

M.A.N. TGE 3.140 Koelwagen Export!



Itemno 305422
Kind Van
Specification Frigo
Matriculation year 2018 / 06
Mileage 315,314 km

Chassisnumber
WMA08VUZ1J9005898

Technical condition

Remarks
Carrier-Koelwagen Zijdeur Spoiler Export
(A15)

Price € 17900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,995 kg
Gross vehicle weight 3,500 kg
Wheelbase 364 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Color white
Heated mirrors ✓

Drivetrain

Engine capacity 103 Kw (140 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Inner box length 342 cm
Inner box width 190 cm
Inner box height 190 cm
Load bed height 95 cm
Rear step ✓
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth
Comfort seat left

Refrigeration unit

Enginename frigo-unit Carrier
Enginetype frigo-unit xarios 350
Enginetype frigo-unit Compressor / electrical
Type of cooling Cooling and freezing
Day/night cooling day and night cooling

Remarks

Remarks Carrier-Koelwagen Zijdeur
Spoiler Export Automaat Euro6!

Tyres/Wheels

Sparewheel ✓
Spare tire profile 7 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho



Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Superstructure



Internal condition



External condition



Refrigeration unit

Systems



Tyres/Wheels

Tyres



1



Tire size: 235/65R16,0
coil spring suspension
Disc brakes

2



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements