

RENAULT MAXITY Bakwagen Deuren!



Itemno 305455
Kind Van
Specification Closed box
Matriculation year 2013 / 01
Mileage 199,106 km

Chassisnumber
VF6SPTF24C3151235

Technical condition

Remarks
Bakwagen Deuren XXL Dubbellucht 136Pk!
(A15)

Price € 9450

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires ✓
Loading Capacity 1,020 kg
Own weight 2,480 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 3,500 kg
Wheelbase 340 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Color white
Heated mirrors ✓

Drivetrain

Engine capacity 100 Kw (136 Hp)
Fuel type diesel
Euro 5
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓

Superstructure

Inner box length 484 cm
Inner box width 205 cm
Inner box height 235 cm
Load bed height 90 cm
Netto height 228 cm
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks Bakwagen Deuren XXL
Dubbellucht 136Pk!

Tyres/Wheels

Sparewheel ✓
Spare tire profile 6 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 195/70R15,0
spring suspension
Disc brakes



2

Tire size: 195/70R15,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements