

MERCEDES-BENZ SPRINTER 514 L2H2 Airco Euro6



Itemno 305505
Kind Van
Specification Closed Van
Matriculation year 2017 / 02
Mileage 172,515 km

Chassisnumber
WDB9066531P369484

Technical condition

Remarks
L2H2 Airco PDC Dubbel Lucht Euro6!
(A15)

Price € 18900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	850 kg
Own weight	2,650 kg
Gross vehicle weight	3,500 kg
Wheelbase	367 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Tacho	✓
Airconditioning	✓
Number of airbags	2
Parking assistance	Front and back
Electric windows	✓
Electric mirrors	✓
Partition	✓
Color	Red
maintenance Guide	✓
Heated mirrors	✓

Drivetrain

Engine capacity	105 Kw (143 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Medium length - High roof
Inner box length	333 cm
Inner box width	177 cm
Inner box height	198 cm
Load bed height	68 cm
Netto height	183 cm
Rear step	✓
Roof-rack	standard
Back doors	Double door
Workshop equipment	✓

Chairs

Number of seats	2
Seat cover	cloth
Comfort seat	left and right

Remarks

Remarks	L2H2 Airco PDC Dubbel Lucht Euro6!
---------	------------------------------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	4 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Wheelsuspension

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 195/75R16,0
spring suspension
Disc brakes



2

Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements