

VOLKSWAGEN TRANSPORTER 2.0 TDI L1H1 Airco

KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES



Itemno 305513
Kind Van
Specification Closed Van
Matriculation year 2017 / 07
Mileage 215,822 km

Chassisnumber
WV1ZZZ7HZJH002735

Technical condition

Remarks
L1H1 Airco EDITION 150Pk Navi Euro6!
(A15)

Price €13990



Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	966 kg
Own weight	1,834 kg
Gross vehicle weight	2,800 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Wheelbase	300 cm
Aluminium rims	
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Front and back
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Silver
Metallic	
Heated mirrors	

Drivetrain

Engine capacity	110 Kw (149 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Inner box length	225 cm
Inner box width	163 cm
Inner box height	139 cm
Load bed height	58 cm
Netto height	128 cm
Roof-rack	None
Sidedoors	1
Side windows	4
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L1H1 Airco EDITION 150Pk Navi Euro6!
---------	---

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 245/45R16,0
coil spring suspension
Disc brakes



2
Tire size: 245/45R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements