

MERCEDES-BENZ VITO 114 L2 Lang Tourer Pro!



Itemno 305619
 Kind Van
 Specification Passenger transport
 Matriculation year 2020 / 07
 Mileage 143,633 km
Chassisnumber
 W1V44770313723781
 Technical condition
Remarks
 L2 Lang Tourer Pro Airco Camera Navigatie
 (A15)

Price € 24900



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
 P.O. Box 3
 4214 ZJ Vuren
 Zeiving 12
 4214 KT Vuren
 The Netherlands

IBAN: NL32RABO0317847430
 SWIFT/BIC: RABONL2U

KvK 11044363
 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
 Configuration 4x2
 Own weight 2,144 kg
 Gross vehicle weight 3,100 kg
 Wheelbase 320 cm
 Suspension type coil spring suspension

Cabin

Cruise control ✓
 Airconditioning ✓
 Number of airbags 4
 Rear wiper ✓
 Parking assistance Front and back
 Electric windows ✓
 Electric mirrors ✓
 GPS navigation ✓
 Color Black
 maintenance Guide ✓
 Heated mirrors ✓
 Reversing camera ✓

Drivetrain

Engine capacity 105 Kw (143 Hp)
 Fuel type diesel
 Euro 6
 Distribution type Timing chain
 Gearbox kind Manual
 Number of Gears 6
 Power steering ✓
 ABS ✓
 ASR ✓

Superstructure

Build kind Medium length - Standard roof
 Inner box length 61 cm
 Inner box width 142 cm
 Inner box height 128 cm
 Load bed height 52 cm
 Netto height 118 cm
 Roof-rack None
 Sidedoors 1
 Back doors taillift

Chairs

Number of seats 9
 Seat cover cloth

Remarks

Remarks L2 Lang Tourer Pro Airco
 Camera Navigatie
 Personenvervoer 1e Eigenaar!

Tyres/Wheels

Sparewheel ✓
 Spare tire profile 8 mm

Contact information




info@kleyn.com
 Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/55R17,0
coil spring suspension
Disc brakes



Tire size: 225/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements