

CITROEN JUMPER 3.0 180Pk DubbelCabine!



Itemno 305630
Kind Van
Specification Closed Van
Matriculation year 2014 / 02
Mileage 242,705 km

Chassisnumber
VF7YDPMFC12572106

Technical condition 

Remarks
3.0Ltr 180Pk DubbelCabine Imperiaal L3H2!
(A15)

Price € 9450



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Own weight 2,290 kg
Gross vehicle weight 3,500 kg
Towing bracket √
Wheelbase 404 cm
Suspension type spring suspension

Cabin

Cabin type double cabin
Number of airbags 2
Parking assistance None
Coloured windows √
Electric windows √
Electric mirrors √
Partition √
Color Black
Metallic √
Heated mirrors √

Drivetrain

Engine capacity 130 Kw (177 Hp)
Fuel type diesel
Euro 5
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering √
ABS √
ASR √

Superstructure

Inner box length 290 cm
Inner box width 187 cm
Inner box height 194 cm
Load bed height 52 cm
Netto height 177 cm
Roof-rack with roll and stairs
Sidedoors 1
Side windows 2
Back doors Double door

Chairs

Number of seats 6
Seats configuration 3+3
Seat cover cloth

Remarks

Remarks 3.0Ltr 180Pk DubbelCabine
Imperiaal L3H2!

Tyres/Wheels

Sparewheel √

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Fuel system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 225/75R16,0
coil spring suspension
Disc brakes



2

Tire size: 225/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements