

MERCEDES-BENZ SPRINTER 319 L2H2 Airco 3.0L V6



Itemno 305679
Kind Van
Specification Closed Van
Matriculation year 2016 / 06
Mileage 265,709 km

Chassisnumber
WDB9066331P284186

Technical condition

Remarks
L2H2 Airco Automaat 3.0L V6 1e Eigenaar!
(A15)

Price € 17900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,085 kg
Own weight	2,415 kg
Gross vehicle weight	3,500 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	3,500 kg
Towing bracket	✓
Wheelbase	367 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Tacho	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Coloured windows	✓
Electric windows	✓
Electric mirrors	✓
Partition	✓
Color	Blue
maintenance Guide	✓
Heated mirrors	✓

Drivetrain

Engine capacity	140 Kw (190 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Number of Gears	7
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Medium length - High roof
Inner box length	331 cm
Inner box width	177 cm
Inner box height	197 cm
Load bed height	63 cm
Netto height	184 cm
Roof-rack	None
Sidedoors	1
Side windows	1
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	L2H2 Airco Automaat 3.0L V6 1e Eigenaar!
---------	---

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 235/65R16,0
spring suspension
Disc brakes



2

Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements