

RENAULT KANGOO 1.5 DCI 110 FRIGO



Itemno 305800
Kind Van
Specification Frigo
Matriculation year 2018 / 12
Mileage 234,733 km

Chassisnumber
VF1FW52N262004246

Technical condition

Remarks
koelwagen, dag/nacht, airco
(A15)

Price €10900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 408 kg
Own weight 1,692 kg
Gross vehicle weight 2,100 kg
Unbraked towing capacity 680 kg
Braked towing capacity, center axle 1,050 kg
Wheelbase 270 cm
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Cruise control
Airconditioning
Number of airbags 1
Parking assistance Back
Electric windows
Electric mirrors
Partition
GPS navigation
Color white
Heated mirrors
Reversing camera

Drivetrain

Engine capacity 81 Kw (110 Hp)
Fuel type diesel
Euro 6
Distribution type Timing belt
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Inner box length 140 cm
Inner box width 127 cm
Inner box height 103 cm
Load bed height 59 cm
Netto height 98 cm
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 2
Seat cover cloth

Refrigeration unit

Day/night cooling day and night cooling

Remarks

Remarks koelwagen, dag/nacht, airco

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/65R15,0
coil spring suspension
Disc brakes



Tire size: 195/65R15,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements