

VOLKSWAGEN CADDY 2.0 TDI L2 Maxi DSG!



Itemno 305829
Kind Van
Specification Compact panel van
Matriculation year 2019 / 07
Mileage 183,123 km

Chassisnumber
WV1ZZZ2KZX083187

Technical condition

Remarks
L2 Maxi Airco Automaat DSG MF Stuurwiel
(A15)

Price € 12900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	786 kg
Own weight	1,540 kg
Gross vehicle weight	2,326 kg
Unbraked towing capacity	740 kg
Braked towing capacity, center axle	1,500 kg
Wheelbase	301 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	2
Rear wiper	✓
Parking assistance	Back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	Gray
Metallic	✓
maintenance Guide	✓
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	75 Kw (102 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Number of Gears	7
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Medium length - Standard roof
Inner box length	208 cm
Inner box width	150 cm
Inner box height	127 cm
Load bed height	56 cm
Netto height	114 cm
Roof-rack	None
Sidedoors	2
Side windows	1
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L2 Maxi Airco Automaat DSG MF Stuurwiel Navi 102 PK 1e Eigenaar!
---------	--

Tyres/Wheels

Sparewheel	✓
Spare tire profile	6 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1
Tire size: 195/65R15,0
coil spring suspension
Disc brakes



2
Tire size: 195/65R15,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements