

MERCEDES-BENZ SPRINTER 316 L2H2 Trekhaak 16



Itemno 305871
Kind Van
Specification Closed Van
Matriculation year 2010 / 02
Mileage 151,466 km

Chassisnumber
WDB9066331S449208

Technical condition

Remarks
L2H2 Trekhaak 163PK!
(A15)

Price €10900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	944 kg
Own weight	2,256 kg
Gross vehicle weight	3,200 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,800 kg
Towing bracket	
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Tacho	
Number of airbags	2
Parking assistance	None
Electric windows	
Electric mirrors	
Partition	
Color	Silver
Metallic	
maintenance Guide	
Heated mirrors	
Reversing camera	

Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Build kind	Medium length - High roof
Inner box length	333 cm
Inner box width	177 cm
Inner box height	197 cm
Load bed height	68 cm
Rear step	
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	L2H2 Trekhaak 163PK!
---------	----------------------

Tyres/Wheels

Sparewheel	
------------	--

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 235/65R16,0
spring suspension
Disc brakes



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements