

## PEUGEOT BOXER 2.0 BlueHDI 130 L3H2



Itemno 305942  
Kind Van  
Specification Closed Van  
Matriculation year 2018 / 10  
Mileage 98,157 km

**Chassisnumber**  
VF3YD2MFC12H91036

Technical condition 

**Remarks**  
L3H2, airco, navi, pdc, trekhaak, 98 dkm.,  
( A15 )

**Price €17900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles 2  
Configuration 4x2  
Loading Capacity 1,510 kg  
Own weight 1,990 kg  
Gross vehicle weight 3,500 kg  
Unbraked towing capacity 750 kg  
Braked towing capacity, center axle 3,000 kg  
Towing bracket  
Wheelbase 404 cm  
Suspension type spring suspension

### Cabin

Cabin type single cabin  
Cruise control  
Airconditioning  
Number of airbags 2  
Parking assistance None  
Electric windows  
Electric mirrors  
Partition  
Color white  
maintenance Guide  
Heated mirrors

### Drivetrain

Engine capacity 96 Kw (130 Hp)  
Fuel type diesel  
Euro 6  
Distribution type Timing belt  
Gearbox kind Manual  
Number of Gears 6  
Power steering  
ABS  
ASR

### Superstructure

Inner box length 350 cm  
Inner box width 186 cm  
Inner box height 197 cm  
Load bed height 52 cm  
Netto height 182 cm  
Rear step  
Roof-rack None  
Sidedoors 1  
Back doors Double door

### Chairs

Number of seats 2  
Seat cover cloth

### Remarks

Remarks L3H2, airco, navi, pdc,  
trekhaak, 98 dkm., side bars

### Tyres/Wheels

Sparewheel

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Clutch

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1  
Tire size: 215/75R16,0  
coil spring suspension  
Disc brakes



2  
Tire size: 215/75R16,0  
spring suspension  
Disc brakes

## Contact information



info@kleyn.com

Tel: +31 183 668 444

## Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements