IVECO DAILY 35 S 150 L2H2



305946 Itemno Kind Van Specification Closed Van Matriculation year 2015 / 05 Mileage 150,068 km

Chassisnumber

ZCFC135A605035263

Technical condition

Remarks

L2H2, airco, 150 dkm.

(A15)





Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 2,406 kg Own weight Gross vehicle weight 3,500 kg Wheelbase 352 cm

Suspension type spring suspension

Cabin

Cabin type single cabin Cruise control

Airconditioning

Number of airbags 1 Parking assistance None

Coloured windows Electric windows

Electric mirrors

Partition

Color white

Drivetrain

Power steering

107 Kw (145 Hp) Engine capacity

Fuel type diesel Euro

Distribution type Timing belt Gearbox kind Manual Number of Gears

ASR

Superstructure

Inner box length 356 cm Inner box width 181 cm 196 cm Inner box heigth Load bed heigth 78 cm

Rear step

Roof-rack None Sidedoors

Double door Back doors

Chairs

Number of seats 3 Seat cover cloth

Remarks

Remarks L2H2, airco, 150 dkm.

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional














Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



VANS

LEYN KLEYN K

TRAILERS



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general 00000 33330 Cooling system 00000 Fuel system 0000 Exhaust system 00000 Greasing system Gearbox 3330 Clutch 00000 Drivetrain 33330

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



spring suspension
Disc brakes



Tire size: 225/65R16,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state
Moderate state

Does not meet requirements