

MERCEDES-BENZ EVITO L2 Airco Elektrisch!



Itemno 305959
Kind Van
Specification Closed Van
Matriculation year 2019 / 11
Mileage 7,659 km

Chassisnumber
WDF44760313665603

Technical condition

Remarks
L2 Lang Airco Achterdeuren 100& Elektrisch
(A15)

Price € 17900

KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Loading Capacity 1,042 kg
Own weight 2,158 kg
Gross vehicle weight 3,200 kg
Wheelbase 320 cm
Suspension type coil spring suspension

Cabin

Cabin type single cabin
Airconditioning ✓
Number of airbags 2
Parking assistance None
Electric windows ✓
Partition ✓
Color white
maintenance Guide ✓
Reversing camera ✓

Drivetrain

Engine capacity (0 Hp)
Fuel type electrical
Gearbox kind Automatic
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Build kind Medium length - Standard roof
Inner box length 250 cm
Inner box width 166 cm
Inner box height 136 cm
Load bed height 58 cm
Netto height 123 cm
Roof-rack None
Back doors Double door

Chairs

Number of seats 3
Seat cover cloth

Remarks

Remarks L2 Lang Airco Achterdeuren
100& Elektrisch 1e Eigenaar!

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Wheelsuspension

Brakes

Drivetrain

Engine, general

Cooling system

Greasing system

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 225/55R17,0
coil spring suspension
Disc brakes



Tire size: 225/55R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements