VOLKSWAGEN CRAFTER 35 2.0 L3H2 Airco Trekha



Itemno 306060 Kind Van Specification Closed Van Matriculation year 2018 / 02 Mileage 169,372 km

Chassisnumber WV1ZZZSYZH9004141

Technical condition

Remarks L3H2 Airco Mf-Stuurwiel CarPlay Trekhaak (A15)







Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 Loading Capacity 1,472 kg Own weight 2,028 kg Gross vehicle weight 3,500 kg Unbraked towing capacity 750 kg Braked towing capacity, center 3,000 kg

Towing bracket

Wheelbase 364 cm

Suspension type spring suspension

Cabin

Cabin type single cabin

Cruise control

Airconditioning Number of airbags

Parking assistance Front and back

Electric windows

Electric mirrors

Partition

Color white

Heated mirrors

Drivetrain

Engine capacity 103 Kw (140 Hp)

Fuel type diesel Euro

Distribution type Timing belt Gearbox kind Manual Number of Gears 6

Power steering

ABS **ASR**

Superstructure

Inner box length 320 cm Inner box width 178 cm 168 cm Inner box heigth Load bed heigth 61 cm Netto height 156 cm

Rear step

Roof-rack None Sidedoors

Back doors Double door

Chairs

Number of seats 3 Seat cover cloth

Remarks

Remarks L3H2 Airco Mf-Stuurwiel

CarPlay Trekhaak 140Pk

Euro6!

Tyres/Wheels

Sparewheel

6 mm Spare tire profile

Contact information



info@kleyn.com Tel: +31 183 668 444

Certified and professional
















Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KL = YN VANS

GROUP KLEYN KL

TRAILERS



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general 33330 Cooling system 00000 Fuel system 0000 Exhaust system 00000 Greasing system Gearbox 3330 Clutch 00000 Drivetrain 33330

Superstructure

Internal condition

External condition

Tyres/Wheels

Tires and axles



Tire size: 205/75R16,0 coil spring suspension Disc brakes



Tire size: 205/75R16,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state
Moderate state

Does not meet requirements