

MERCEDES-BENZ SPRINTER 516 CDI



Itemno 306102
Kind Van
Specification Closed Van
Matriculation year 2016 / 12
Mileage 320,223 km

Chassisnumber
WDB9066531P271840

Technical condition

Remarks
L2H2 AC DUBBELLUCHT MOTOR
(A15)

Price € 9950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires ✓
Own weight 2,466 kg
Gross vehicle weight 3,500 kg
Wheelbase 367 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control ✓
Airconditioning ✓
Number of airbags 1
Parking assistance None
Electric windows ✓
Electric mirrors ✓
Partition ✓
Color white
Reversing camera ✓

Drivetrain

Engine capacity 120 Kw (163 Hp)
Fuel type diesel
Euro 5
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering ✓
ABS ✓
ASR ✓

Superstructure

Build kind Medium length - High roof
Inner box length 333 cm
Inner box width 177 cm
Inner box height 196 cm
Load bed height 68 cm
Netto height 181 cm
Rear step ✓
Roof-rack None
Sidedoors 1
Back doors Double door

Chairs

Number of seats 2
Seat cover cloth
Comfort seat left

Remarks

Remarks L2H2 AC DUBBELLUCHT
MOTOR KAPOT!!!

Tyres/Wheels

Sparewheel ✓
Spare tire profile 8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 195/75R16,0
spring suspension
Disc brakes



2

Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements