

MERCEDES-BENZ SPRINTER 514 Bakwagen Laadklep



Itemno 306302
Kind Van
Specification Closed box
Matriculation year 2020 / 03
Mileage 105,900 km

Chassisnumber
W1V9071551N079119

Technical condition

Remarks
Bakwagen Laadklep Airco Dubbellucht
(A15)

Price €28750

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles 2
Configuration 4x2
Twin tires
Loading Capacity 572 kg
Own weight 2,928 kg
Gross vehicle weight 3,500 kg
Unbraked towing capacity 750 kg
Braked towing capacity, center axle 2,000 kg
Wheelbase 433 cm
Suspension type spring suspension

Cabin

Cabin type single cabin
Cruise control
Airconditioning
Number of airbags 1
Parking assistance None
Electric windows
Electric mirrors
Color white
Heated mirrors

Drivetrain

Engine capacity 105 Kw (143 Hp)
Fuel type diesel
Euro 6
Distribution type Timing chain
Gearbox kind Manual
Number of Gears 6
Power steering
ABS
ASR

Superstructure

Roof-rack None
Back doors taillift

Chairs

Number of seats 3
Seat cover cloth

Taillift

Taillift
Tail-lift kind normal
Tail-lift capacity 750 kg
Tail-lift make DHOLLANDIA
Tail-lift size 144 x 211

Remarks

Remarks Bakwagen Laadklep Airco
Dubbellucht 143Pk Euro6!

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Superstructure

Internal condition

External condition

Taillift

Controls

System

Tyres/Wheels

Tyres



1



Tire size: 195/75R16,0
spring suspension
Disc brakes

2



Tire size: 195/75R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com
Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements