

VOLKSWAGEN LT 46 2.5 TDI



Itemno 306306
Kind Van
Specification Closed box
Matriculation year 2007 / 04
Mileage 30,281 km

Chassisnumber
WV1ZZZ2DZ6H034346

Technical condition

Remarks
UNIEKE KM STAND AC YOUNGTIMER!!
(A15)

Price € 13950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Twin tires	✓
Loading Capacity	829 kg
Own weight	2,671 kg
Gross vehicle weight	3,500 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	✓
Wheelbase	404 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Tacho	✓
Airconditioning	✓
Parking assistance	None
Electric windows	✓
Color	Beige

Drivetrain

Engine capacity	80 Kw (109 Hp)
Fuel type	diesel
Euro	3
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	5
Power steering	✓
ABS	✓

Superstructure

Build kind	Extra long - Standard roof
Inner box length	420 cm
Inner box width	207 cm
Inner box height	207 cm
Load bed height	85 cm
Netto height	206 cm
Rear step	✓
Roof-rack	None
Sidedoors	1
Back doors	Double door
Workshop equipment	✓

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	UNIEKE KM STAND AC YOUNGTIMER!!
---------	---------------------------------

Tyres/Wheels

Sparewheel	✓
Spare tire profile	8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/70R15,0
torsion spring suspension
Disc brakes



Tire size: 195/70R15,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements