# VOLKSWAGEN TRANSPORTER 2.0 TDI T6.1 150Pk



Itemno Kind Specification Matriculation year Mileage Chassisnumber WV1ZZZ7HZLX016239

306454 Van Closed Van 2020 / 06



a a a

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

KLEYN

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KLEYN

KvK 11044363 BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Wheelbase Suspension type

### Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Coloured windows Electric windows Electric mirrors Partition **GPS** navigation Color Metallic maintenance Guide Heated mirrors

### Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

2 4x2 996 kg 1,804 kg 2,800 kg 750 kg 2,200 kg

300 cm coil spring suspension

single cabin

2 Back

Gray

81 Kw (110 Hp) diesel 6 Timing belt Manual 6

## Superstructure

Inner box length Inner box width Inner box heigth Load bed heigth Roof-rack Back doors

Chairs Number of seats Seat cover

#### Remarks Remarks

**Tyres/Wheels** Sparewheel

245 cm 164 cm 142 cm 64 cm None Double door

3 cloth

L1H1, airco, navi, pdc, nwe. type.

#### Certified and professional




Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

### **Contact information**



info@kleyn.com Tel: +31 183 668 444

## **Dimensions**



## **Inspection report**

Chassis	
Dashboard display codes	0000
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	
Tyres/Wheels	

Tyres

#### **Contact information**



info@kleyn.com Tel: +31 183 668 444

VANS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

## **Tires and axles**



Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements