

OPEL VIVARO 1.6 L2H1 Navi 140Pk AC!



Itemno 306624
Kind Van
Specification Closed Van
Matriculation year 2014 / 12
Mileage 190,167 km

Chassisnumber
W0L1F7119FS010802

Technical condition 

Remarks
L2H1 Navi 140Pk AC Lm-Velgen Sidebars
(A15)



Price €10950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,295 kg
Own weight	1,685 kg
Gross vehicle weight	2,980 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	350 cm
Aluminium rims	
Suspension type	coil spring suspension

Cabin

Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Back
Coloured windows	
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	Black
Heated mirrors	
Reversing camera	

Drivetrain

Engine capacity	103 Kw (140 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

Superstructure

Boxmaterial	isolated
Inner box length	294 cm
Inner box width	164 cm
Inner box height	136 cm
Load bed height	57 cm
Netto height	136 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L2H1 Navi 140Pk AC Lm-Velgen Sidebars Trekhaak NAP!
---------	-----------------------------------------------------------

Tyres/Wheels

Sparewheel	
Spare tire profile	8 mm

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 215/60R17,0
coil spring suspension
Disc brakes



2

Tire size: 215/60R17,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements