RENAULT MASTER T33 2.3 DCI



Itemno Kind Specification Matriculation year Mileage Chassisnumber VF1MA000560302454

306689 Van Closed Van 2019/01 110,435 km



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration Loading Capacity Own weight Gross vehicle weight Unbraked towing capacity Braked towing capacity, center axle Towing bracket Wheelbase Suspension type

Cabin

Cabin type Cruise control Airconditioning Number of airbags Parking assistance Electric windows Electric mirrors Partition Color Reversing camera

Drivetrain

Engine capacity Fuel type Euro Distribution type Gearbox kind Number of Gears Power steering ABS ASR

4x2 1,396 kg 1,904 kg 3,300 kg 750 kg 2,500 kg

2

368 cm spring suspension

single cabin

1 Back

white

81 Kw (110 Hp) diesel 6 Timing chain Manual 6

Superstructure

NAP

Build kind Inner box length Inner box width Inner box heigth Load bed heigth Netto height Roof-rack Sidedoors Back doors

Chairs

Number of seats Seat cover

Tyres/Wheels

Sparewheel

Medium length - High roof 300 cm 175 cm 187 cm 58 cm 180 cm with roll and stairs 1 Double door

3 cloth

Contact information




info@kleyn.com Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



Inspection report

Chassis	
Dashboard display codes	
Electrical	
Cabin	
Internal	
External	
Steering column	
Suspension	
Chassis	
Brakes	
Drivetrain	
Engine, general	
Cooling system	
Fuel system	
Exhaust system	
Greasing system	
Gearbox	
Clutch	
Drivetrain	
Superstructure	
Internal condition	
External condition	0000
Tyres/Wheels	

Tyres

Contact information



info@kleyn.com Tel: +31 183 668 444


VANS

Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Tires and axles



Spring suspension Disc brakes

Legenda for inspection report Very good state Good state Reasonable state Moderate state Does not meet requirements