

CITROEN BERLINGO 1.5 HDI L1H1 Airco 102PK



Itemno 306739
Kind Van
Specification Compact panel van
Matriculation year 2022 / 07
Mileage 123,034 km

Chassisnumber
VR7EFYHT2NN524595

Technical condition

Remarks
L1H1 Airco 102PK 1e Eigenaar Org NL!
(A15)

Price € 12900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	683 kg
Own weight	1,337 kg
Gross vehicle weight	2,020 kg
Unbraked towing capacity	710 kg
Braked towing capacity, center axle	1,500 kg
Towing bracket	✓
Wheelbase	279 cm
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Partition	✓
Color	white
maintenance Guide	✓
Heated mirrors	✓

Drivetrain

Engine capacity	75 Kw (102 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Standard length - Standard roof
Inner box length	161 cm
Inner box width	131 cm
Inner box height	123 cm
Load bed height	52 cm
Netto height	115 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L1H1 Airco 102PK 1e Eigenaar Org NL!
---------	--------------------------------------

Tyres/Wheels

Sparewheel	✓
------------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 

Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Brakes 

Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

Superstructure

Internal condition 

External condition 

Tyres/Wheels

Tyres 

Tires and axles



Tire size: 195/65R15,0
coil spring suspension
Disc brakes



Tire size: 195/65R15,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

 Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements