

OPEL COMBO 1.6 L2H1 2xZijdeur Airco



Itemno 306990
Kind Van
Specification Compact panel van
Matriculation year 2017 / 11
Mileage 133,512 km

Chassisnumber
W0L6WZR1BJ9626642

Technical condition

Remarks
L2H1 2xZijdeur Airco Trekhaak 105Pk
(A15)



Price €8700

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,053 kg
Own weight	1,405 kg
Gross vehicle weight	2,458 kg
Unbraked towing capacity	500 kg
Braked towing capacity, center axle	1,300 kg
Towing bracket	
Wheelbase	311 cm
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	2
Parking assistance	Back
Electric windows	
Electric mirrors	
Partition	
Color	white
maintenance Guide	
Heated mirrors	

Drivetrain

Engine capacity	77 Kw (105 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Power steering	
ABS	
ASR	

Superstructure

Inner box length	175 cm
Inner box width	144 cm
Inner box height	129 cm
Load bed height	51 cm
Netto height	120 cm
Roof-rack	None
Sidedoors	2
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L2H1 2xZijdeur Airco Trekhaak 105Pk Wp-Inrichting Oh-Historie Euro6!
---------	--

Tyres/Wheels

Sparewheel

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430


SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes 

Electrical 

Cabin

Internal 

External 

Steering column 

Suspension 

Chassis 

Brakes 


Drivetrain

Engine, general 

Cooling system 

Fuel system 

Exhaust system 

Greasing system 

Gearbox 

Clutch 

Drivetrain 

Superstructure

Internal condition 

External condition 

Tyres/Wheels

Tyres 

Tires and axles



Tire size: 195/60R16,0
coil spring suspension
Disc brakes



Tire size: 195/60R16,0
coil spring suspension
Drum brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

 Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements