IVECO DAILY 35S12 L2H2 Airco Facelift!



307103 Itemno Kind Van Specification Closed Van Matriculation year 2021 / 11 Mileage 103,646 km

Chassisnumber ZCFC3358305431139

Technical condition







L2H2 Airco 116PK Euro6 1e Eigenaar!

(A15)

Price €21450



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren

Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles Configuration 4x2 1,316 kg Loading Capacity Own weight 2,184 kg 3,500 kg Gross vehicle weight Unbraked towing capacity 750 kg Braked towing capacity, center 3,500 kg

Wheelbase 352 cm

Suspension type spring suspension

Cabin

Cabin type single cabin

Cruise control Airconditioning

Number of airbags Parking assistance Back

Electric windows Electric mirrors

Partition

Color

maintenance Guide Heated mirrors Reversing camera

Drivetrain

85 Kw (116 Hp)

white

Fuel type Euro

Distribution type Timing belt Gearbox kind Manual Number of Gears

Power steering

ABS **ASR**

Superstructure

Build kind Medium length - High roof

Inner box length 352 cm 181 cm Inner box width 205 cm Inner box heigth Load bed heigth 68 cm Netto height 178 cm

Rear step

Roof-rack None

Back doors Double door

Chairs

Number of seats 3 Seat cover cloth

Remarks

Remarks L2H2 Airco 116PK Euro6 1e

Eigenaar!

Engine capacity

diesel

Certified and professional















Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.





info@kleyn.com Tel: +31 183 668 444

Dimensions



VANS

LEYN KLEYN K





Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general 00000 33330 Cooling system 00000 Fuel system 0000 Exhaust system 00000 Greasing system Gearbox 3330 Clutch 00000 Drivetrain 33330

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



spring suspension
Disc brakes



Tire size: 225/65R16,0 spring suspension Disc brakes

Contact information



info@kleyn.com Tel: +31 183 668 444

Legenda for inspection report

Very good state
Good state
Reasonable state
Moderate state

Does not meet requirements