### FORD TRANSIT 2.0 TDCI 170 L2H2



307114 Itemno Kind Van Specification Closed Van Matriculation year 2017 / 03 Mileage 246,100 km

Chassisnumber

WF0XXXTTGXHJ39904

Technical condition

Remarks

L2H2, 2x zijdeur, airco, navi, pdc, trekhaak

(A15)













Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

# **Equipment**

### Chassis

Number of axles Configuration 4x2 **Loading Capacity** 1,231 kg Own weight 2,269 kg 3,500 kg Gross vehicle weight Unbraked towing capacity 750 kg Braked towing capacity, center 2,800 kg

Towing bracket

330 cm Wheelbase

Suspension type spring suspension

### Cabin

Cabin type single cabin

Cruise control

Tacho

Airconditioning Parking heater

Number of airbags

Parking assistance Front and back

Electric windows Electric mirrors

Partition

Color white

maintenance Guide Heated mirrors Reversing camera

### **Drivetrain**

Engine capacity 125 Kw (170 Hp)

diesel Euro

Distribution type Timing belt Gearbox kind Manual Number of Gears

Power steering

ABS **ASR** 

### Superstructure

Inner box length 290 cm Inner box width 173 cm 175 cm Inner box heigth Load bed heigth 71 cm Netto height 158 cm

Rear step

Roof-rack None Sidedoors

Back doors Double door

### Chairs

Number of seats 3 Seat cover cloth

### Remarks

Remarks L2H2, 2x zijdeur, airco, navi,

pdc, trekhaak

Fuel type

## Certified and professional















Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.





info@kleyn.com Tel: +31 183 668 444

### **Dimensions**



# VANS

LEYN KLEYN KL GROUP TRUCKS

KLEYN



Kleyn Vans B.V.® P.O. Box 3 4214 ZJ Vuren Zeiving 12 4214 KT Vuren The Netherlands

IBAN: NL32RABO0317847430 SWIFT/BIC: RABONL2U

KvK 11044363 BTW/VAT NL807901337B01

# **Inspection report**

### Chassis

Tacho

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general 0000 0000 Cooling system 33330 Fuel system 00000 Exhaust system Greasing system 3330 Gearbox 00000 Clutch 33330 Drivetrain 00000

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

# Tires and axles



Tire size: 235/65R16,0 coil spring suspension Disc brakes



Tire size: 235/65R16,0 spring suspension Disc brakes

### **Contact information**



info@kleyn.com Tel: +31 183 668 444

### Legenda for inspection report

Very good state
Good state
Reasonable state

Moderate state

Does not meet requirements