

## FORD TRANSIT 2.0 TDCI 130 AUT. L1H1



Itemno 307115  
Kind Van  
Specification Closed Van  
Matriculation year 2019 / 06  
Mileage 126,774 km

**Chassisnumber**  
WF0YXXTTGYKL52589

Technical condition

**Remarks**  
L1H1, automaat, airco, pdc  
( A15 )

**Price € 17900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

|                                     |                        |
|-------------------------------------|------------------------|
| Number of axles                     | 2                      |
| Configuration                       | 4x2                    |
| Loading Capacity                    | 990 kg                 |
| Own weight                          | 2,010 kg               |
| Gross vehicle weight                | 3,000 kg               |
| Unbraked towing capacity            | 750 kg                 |
| Braked towing capacity, center axle | 1,000 kg               |
| Wheelbase                           | 293 cm                 |
| Suspension type                     | coil spring suspension |

### Cabin

|                    |                |
|--------------------|----------------|
| Cabin type         | single cabin   |
| Cruise control     | ✓              |
| Airconditioning    | ✓              |
| Number of airbags  | 1              |
| Parking assistance | Front and back |
| Electric windows   | ✓              |
| Electric mirrors   | ✓              |
| Partition          | ✓              |
| Color              | white          |
| maintenance Guide  | ✓              |
| Heated mirrors     | ✓              |

### Drivetrain

|                   |                |
|-------------------|----------------|
| Engine capacity   | 96 Kw (130 Hp) |
| Fuel type         | diesel         |
| Euro              | 6              |
| Distribution type | Timing chain   |
| Gearbox kind      | Automatic      |
| Power steering    | ✓              |
| ABS               | ✓              |
| ASR               | ✓              |

### Superstructure

|                  |             |
|------------------|-------------|
| Inner box length | 244 cm      |
| Inner box width  | 165 cm      |
| Inner box height | 145 cm      |
| Load bed height  | 54 cm       |
| Netto height     | 133 cm      |
| Roof-rack        | None        |
| Sidedoors        | 1           |
| Back doors       | Double door |

### Chairs

|                 |       |
|-----------------|-------|
| Number of seats | 3     |
| Seat cover      | cloth |

### Remarks

|         |                            |
|---------|----------------------------|
| Remarks | L1H1, automaat, airco, pdc |
|---------|----------------------------|

### Tyres/Wheels

|            |   |
|------------|---|
| Sparewheel | ✓ |
|------------|---|

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN** GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



1

Tire size: 215/65R16,0  
coil spring suspension  
Disc brakes



2

Tire size: 215/65R16,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements