

## OPEL VIVARO 1.6 CDTI 120 SPORT L2



Itemno 307214  
Kind Van  
Specification Closed Van  
Matriculation year 2016 / 08  
Mileage 160,618 km

**Chassisnumber**  
W0L2F7118GV640370

Technical condition 

### Remarks

lang, SPORT, airco, navi, pdc, trekhjaak  
( A15 )



**Price €11900**

# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®  
P.O. Box 3  
4214 ZJ Vuren  
Zeiving 12  
4214 KT Vuren  
The Netherlands

IBAN: NL32RABO0317847430  
SWIFT/BIC: RABONL2U

KvK 11044363  
BTW/VAT NL807901337B01

## Equipment

### Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,299 kg
Own weight	1,711 kg
Gross vehicle weight	3,010 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,000 kg
Towing bracket	
Wheelbase	350 cm
Suspension type	coil spring suspension

### Cabin

Cabin type	single cabin
Cruise control	
Airconditioning	
Number of airbags	1
Parking assistance	Back
Electric windows	
Electric mirrors	
Partition	
GPS navigation	
Color	white
maintenance Guide	
Reversing camera	

### Drivetrain

Engine capacity	88 Kw (120 Hp)
Fuel type	diesel
Euro	5
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	
ABS	
ASR	

### Superstructure

Inner box length	270 cm
Inner box width	164 cm
Inner box height	137 cm
Load bed height	55 cm
Netto height	130 cm
Roof-rack	None
Sidedoors	1
Back doors	Double door

### Chairs

Number of seats	3
Seat cover	cloth

### Remarks

Remarks	lang, SPORT, airco, navi, pdc, trekhjaak
---------	--

### Tyres/Wheels

Sparewheel	
Spare tire profile	6 mm

### Contact information




info@kleyn.com  
Tel: +31 183 668 444

### Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

## Dimensions



# KLEYN VANS

**KLEYN GROUP** **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

## Inspection report

### Chassis

Dashboard display codes

Electrical

### Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

### Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

### Superstructure

Internal condition

External condition

### Tyres/Wheels

Tyres

## Tires and axles



Tire size: 205/65R16,0  
coil spring suspension  
Disc brakes



Tire size: 205/65R16,0  
coil spring suspension  
Disc brakes

### Contact information



info@kleyn.com

Tel: +31 183 668 444

### Legenda for inspection report

Very good state  
 Good state  
 Reasonable state  
 Moderate state  
 Does not meet requirements