

MERCEDES-BENZ SPRINTER 316 CDI



Itemno 307297
Kind Van
Specification Closed box
Matriculation year 2016 / 10
Mileage 203,480 km

Chassisnumber
WDB9061351N687908

Technical condition

Remarks
LAADBAK BEKLEED AC STANDKACHEL
(A15)

Price € 18950

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	710 kg
Own weight	2,790 kg
Gross vehicle weight	3,500 kg
Wheelbase	433 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Parking heater	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Color	white
Reversing camera	✓

Drivetrain

Engine capacity	120 Kw (163 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Extra long - Standard roof
Inner box length	435 cm
Inner box width	212 cm
Inner box height	207 cm
Load bed height	93 cm
Netto height	204 cm
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	2
Seat cover	cloth

Taillift

Taillift	✓
Tail-lift kind	normal
Tail-lift capacity	750 kg
Tail-lift make	B.A.R cargolift
Tail-lift size	163x178

Remarks

Remarks	LAADBAK BEKLEED AC STANDKACHEL EURO6
---------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes



Electrical



Cabin

Internal



External



Steering column



Suspension



Chassis



Brakes



Drivetrain

Engine, general



Cooling system



Fuel system



Exhaust system



Greasing system



Gearbox



Clutch



Drivetrain



Superstructure

Internal condition



External condition



Taillift

Controls



System



Tyres/Wheels

Tyres



1



Tire size: 235/65R16,0
spring suspension
Disc brakes

2



Tire size: 235/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

- Very good state
- Good state
- Reasonable state
- Moderate state
- Does not meet requirements