

MERCEDES-BENZ VITO 114 L3 XL Automaat ECC!



Itemno 307315
Kind Van
Specification Closed Van
Matriculation year 2018 / 05
Mileage 229,272 km

Chassisnumber
WDF44760513472013

Technical condition

Remarks
L3 XL Airco/ ECC Automaat Trekhaak
(A15)

Price € 14900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Own weight	2,152 kg
Gross vehicle weight	2,800 kg
Towing bracket	✓
Wheelbase	343 cm
Suspension type	coil spring suspension

Cabin

Cruise control	✓
Airconditioning	✓
Number of airbags	2
Rear wiper	✓
Parking assistance	Front and back
Coloured windows	✓
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	Silver
Metallic	✓
Heated mirrors	✓

Drivetrain

Engine capacity	100 Kw (136 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing chain
Gearbox kind	Automatic
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Inner box length	252 cm
Inner box width	168 cm
Inner box height	134 cm
Load bed height	55 cm
Netto height	125 cm
Roof-rack	None
Sidedoors	1
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L3 XL Airco/ ECC Automaat Trekhaak 136Pk Euro6!
---------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN** TRUCKS **KLEYN** TRAILERS **KLEYN** SERVICES

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Tacho

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 195/65R16,0
coil spring suspension
Disc brakes



Tire size: 195/65R16,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements