

VOLKSWAGEN TRANSPORTER 2.0 TDI L2 Lang Hig



Itemno 307354
Kind Van
Specification Closed Van
Matriculation year 2016 / 10
Mileage 90,580 km

Chassisnumber
WV1ZZZ7HZHH057288

Technical condition 

Remarks
L2 Lang Airco 204PK DSG Automaat
(A15)



Price € 24900

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	1,021 kg
Own weight	1,979 kg
Gross vehicle weight	3,000 kg
Unbraked towing capacity	750 kg
Braked towing capacity, center axle	2,500 kg
Wheelbase	340 cm
Aluminium rims	✓
Suspension type	coil spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	4
Rear wiper	✓
Parking assistance	Back
Electric windows	✓
Electric mirrors	✓
Partition	✓
GPS navigation	✓
Color	Black
Metallic	✓
maintenance Guide	✓
Reversing camera	✓

Drivetrain

Engine capacity	150 Kw (204 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Automatic
Number of Gears	7
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	Medium length - Standard roof
Inner box length	280 cm
Inner box width	157 cm
Inner box height	131 cm
Load bed height	60 cm
Netto height	128 cm
Roof-rack	None
Sidedoors	1
Back doors	taillift

Chairs

Number of seats	2
Seat cover	cloth

Remarks

Remarks	L2 Lang Airco 204PK DSG Automaat Highline!
---------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



Tire size: 255/45R18,0
coil spring suspension
Disc brakes



Tire size: 255/45R18,0
coil spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements