

IVECO DAILY 35S14 Bakwagen Meubelbak!



Itemno 307453
Kind Van
Specification Closed box
Matriculation year 2020 / 12
Mileage 117,896 km

Chassisnumber
ZCFCG35A705364228

Technical condition

Remarks
Bakwagen Meubelbak Airco Euro6 1e
(A15)

Price € 21400

KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®
P.O. Box 3
4214 ZJ Vuren
Zeiving 12
4214 KT Vuren
The Netherlands

IBAN: NL32RABO0317847430
SWIFT/BIC: RABONL2U

KvK 11044363
BTW/VAT NL807901337B01

Equipment

Chassis

Number of axles	2
Configuration	4x2
Loading Capacity	974 kg
Own weight	2,526 kg
Gross vehicle weight	3,500 kg
Wheelbase	345 cm
Suspension type	spring suspension

Cabin

Cabin type	single cabin
Cruise control	✓
Airconditioning	✓
Number of airbags	1
Parking assistance	None
Electric windows	✓
Electric mirrors	✓
Color	white
maintenance Guide	✓
Heated mirrors	✓
Reversing camera	✓

Drivetrain

Engine capacity	100 Kw (136 Hp)
Fuel type	diesel
Euro	6
Distribution type	Timing belt
Gearbox kind	Manual
Number of Gears	6
Power steering	✓
ABS	✓
ASR	✓

Superstructure

Build kind	high roof and extra long
Inner box length	367 cm
Inner box width	221 cm
Inner box height	209 cm
Load bed height	88 cm
Netto height	201 cm
Roof-rack	None
Back doors	Double door

Chairs

Number of seats	3
Seat cover	cloth

Remarks

Remarks	Bakwagen Meubelbak Airco Euro6 1e Eigenaar!
---------	---

Contact information




info@kleyn.com
Tel: +31 183 668 444

Certified and professional



Kleyn Trucks differentiates itself from its competitors by offering expert technical services, safety inspections and repair.

Dimensions



KLEYN VANS

KLEYN GROUP **KLEYN TRUCKS** **KLEYN TRAILERS** **KLEYN SERVICES**

Kleyn Vans B.V.®

P.O. Box 3

4214 ZJ Vuren

Zeiving 12

4214 KT Vuren

The Netherlands

IBAN: NL32RABO0317847430

SWIFT/BIC: RABONL2U

KvK 11044363

BTW/VAT NL807901337B01

Inspection report

Chassis

Dashboard display codes

Electrical

Cabin

Internal

External

Steering column

Suspension

Chassis

Brakes

Drivetrain

Engine, general

Cooling system

Fuel system

Exhaust system

Greasing system

Gearbox

Clutch

Drivetrain

Superstructure

Internal condition

External condition

Tyres/Wheels

Tyres

Tires and axles



1

Tire size: 225/65R16,0
torsion spring suspension
Disc brakes



2

Tire size: 225/65R16,0
spring suspension
Disc brakes

Contact information



info@kleyn.com

Tel: +31 183 668 444

Legenda for inspection report

Very good state
 Good state
 Reasonable state
 Moderate state
 Does not meet requirements